(Hydraulic

ENGINE IDENTIFICATION

Fifth figure of "Vehicle Warranty Number" on car patent plate identifies engine as follows:

Engine Sta	indard - CODE -	Low Compression
221"	L	3
260"	F	8
289" 2-Bbl	С	
4-Bbl	K	
352"	X	
390" 2-Bbl	Υ	
4-Bbl Std	Z	9
4-Bbl Police	P	
Three 2-Bbl	M	
406" One 4-Bbl	В	
Three 2-Bbl	Ğ	
427" One 4-Bbl	Q	
Two 4-Bbl	R	

COMPRESSION PRESSURE

Maximum variation between cylinders engines)	10	lbs	(all
221", 260"	130	0-170	lbs
289", 352"	160	0-200	lbs
390" (10 5-1 Compr Ratio)	160	0-200	lbs
(10 8-1 Compr Ratio)	170	0-210	lbs
406", 427"	160	0-200	lbs
VACUUM READING			
221"	1	6" at	ıdle
260", 289", 352", 390"	1	8" at	ıdle
406", 427"	1	3" at	ıdle

TUNE-UP SPECIFICATIONS VALVE TAPPET CLEARANCE

221" 260"

221 , 200	G 1	Juluullo
289" 2-Bbl	C F	lydraulic
4-Bbl (Cold)	024" In	& Exh
(Hot)	@ 021" Int	& Exh
352"	C I	lydraulic
390" 2 & 4-Bbl Std , Three 2-Bbl	Œ F	lydraulic
4-Bbl Police (Cold)	028" Int	& Exh
(Hot)	@ 025" Int	& Exh
406", 427" (Cold)	028" Int	& Exh
(Hot)	@ 025" Int	& Exh
© - For operating range adjustment		Data
@ - After 30 minutes operation at 1	CUUKPM	

SPARK PLUGS

Gan (All except 427") 032- 036

032- 036"
028- 032"
© 15-20 ft lbs

C - 20-30 ft lbs with new plug in new head

Engine	Spark Plug Type	Autolite No.
221", 260"	Normal and/or Severe Service	BF-42
•	Light Service (Idling, Stop & Go)	BF-82
289" 2-Bbl		BF-42
4-Bbl		BF-32
352"		BF-42
390" 2 & 4	-Bbl Std	BF-42
Three	e 2-Bbl	BF-32
4-Bb	l Police	Œ
406", 427"		BF-32
C - BF-3	2 for energined high eneed. Bl	F-42 for low

C - BF-32 for sustained high speed; BF-42 for low speed, light load

TUNE-UP NOTES

production on this engine Either install this distributor or modify existing distributor (COAF-12127-D or E) as follows: Install Orange Primary Weight Spring, B8A-12192-B, Green Secondary Weight Spring, B7A-12191-B, Blue Vacuum Diaphragm Spring, COTZ-12192-A, and Vacuum Advance Stop, COTZ-12202-A. Adjust Mechanical and Vacuum Advance of modified distributor to specifications listed for C2AF-12127-A (see "Distributor Advance Specifications")

- 2) Replace carburetor Booster Venturi Assembly "FA" (C1AZ-9A523-C) with "F" Booster Venturi Assembly (C0AE-9A523-A) NOTE Carburetors with "F" booster in production identified by orange paint on code tag
 3) Install 1 size leaner main metering jet NOTE Carburetors with this jet installed in production have "B" on code tag after prefix and suffix
- ► 1963 HARD HOT START & FUEL ECONOMY COR-RECTION & PRODUCTION CHANGE: May be caused by excessive choke because choke spring is sensitive to cooler engine compartment air To correct, clamp heater hose to choke housing cover using Clamp C3AZ-18572-A, and three Cover Screws C3AZ-9B874-A NOTE - Heater hose clamped to choke housing on later cars

DISTRIBUTOR

Engine	Point Gap	Cam Angle
221"	014- 016"	26-28½°
260"	© 015- 018"	26-28½°
289" 2-Bbl	014- 016"	26-28°
4-Bbl	019- 021"	₡ 33-36°
352"	014- 016"	26-281/2°
390" All Carbs	014- 016"	26-281/2°
406"	019- 021"	② 33-36°
427" Std Ignition	019- 021"	@ 33-36°
Transistor Ign	019- 021"	© 22-24°

- C 014- 016" on Falcon & Comet with Synchro-mesh
- 2 Both sets operating together (dual points)
- 3 Single points (without condenser)

Breaker Arm Spring Tension

221", 260"	17-20 o∠s
289" 2-Bbl	17-20 ozs
4-Bbl	25-28 ozs
352", 390" All Carbs	17-20 ozs
406"	27-32 ozs
427" Std Ignition	27-30 ozs
Transistor Ignition	21-24 ozs

Condenser Capacity

21-25 mfd for all engines NOTE - No condenser used on 427" with Transistor Ignition

TRANSISTOR IGNITION

See "Ford Motor Co Transistor Ignition" in Electrical Section

- ► 1963 HESITATION ON ACCELERATION CORREC-TION (EARLY CARS). May be caused by improperly seated (staked) accelerator pump ball checks To correct, stake balls properly
- ► HESITATION, STUMBLE, ROUGH ENGINE IDLE CORRECTION (CARS WITH FORD CARBS). See "Automatic Choke Torsion Spring Adjustment" in Ford 2 & 4-Barrel Carburetors in Carburetion Section.
- ► 1958-63 HESITATION OR STUMBLE ON ACCELER-ATION CORRECTION (CARS WITH FORD CARBS): Plastic accelerator pump cavity filler block, No C3OZ-9F565-A, may be installed in accelerator pump cavity if carburetor not already equipped. This filler block used in some late production 1962 cars and in most all 1963 cars
- ► 1963 ENGINE STALLING CORRECTION: May be caused by engine coolant tag being drawn into air cleaner opening To correct, shorten tag wire and relocate tag
- ►TRANSISTOR IGNITION CAUTION: Special procedure for connecting dwell meter, "bumping" engine, and other operations must be followed to prevent damage to transistor ignition system . See "Ford Motor Co. Transistor Ignition" in Electrical Section

- ▶ 1963 VERY ROUGH OR NO IDLE CORRECTION: May be caused by restricted idle fuel jet (check by removing air cleaner and covering idle air bleed with engine running increase in RPM indicates restriction) To correct, thoroughly clean all passages with compressed air
- ► 1963 CARBURETOR MAIN METERING JET SIZE "TAILORING" TO CORRECT FOR RICHNESS OR LEANNESS: A one size richer or leaner jet may be installed in place of the standard jet for better performance, depending on the particular condition NOTE. Make sure any factors contributing to a rich or lean condition have been eliminated before changing jets See "Ford 2 & 4-Barrel Carburetor Jet Specification Table" in Carbureton Section
- ► 1963 221" & 260" ENGINES HARD HOT START & ROUGHIDLE CORRECTION & PRODUCTION CHANGE: May be caused by excess fuel vapors in carburetor bowl To correct, install new air horn, No C3OZ-9524-B, which has smaller internal diameter of vent tubes NOTE This change made in production on December 14, 1962
- ► 1963 352" 2-BBL ENGINE CARBURETOR & DISTRIBUTOR MODIFICATIONS FOR IMPROVED ACCELERATION & FUEL ECONOMY: 1) Distributor C2AF-12127-A used on 390" Engine used on later